

Plinth | 2000

FITTING KNEE TROUGHS TO STANDARD PLINTH





INSERT THREADED KNOB INTO THREADED HOLE

PLACE KNEE TROUGH POLE INTO BRACKET ENSURING THAT THE LONGEST SECTION IS POINTING DOWN



CONNECT KNEE TROUGH TO POLE

PUSH TOGETHER FIRMLY



FINISHED ITEM