

Plinth | 2000


PLINTH LUBRICATION POINTS

PROTECT FLOORING AND UPHOLSTERY WHEN TURNING PLINTH ON ITS SIDE

TURN THE PLINTH ON ITS SIDE WITH THE MOTOR/PUMP UPPER-MOST, SPRAY POINTS "A" "B" AND "C" WITH A GENEROUS AMOUNT OF LUBRICANT, WIPING OFF ANY EXCESS.



TURN THE PLINTH OVER AND REPEAT WITH POINTS "A" "B" "C" AND "D". RETURN PLINTH TO THE UPRIGHT POSITION, AND RAISE AND LOWER.



ONLY USE A GOOD QUALITY LUBRICANT LIKE 3 IN ONE OIL, OR SEWING MACHINE OIL ECT